

EXHIBIT G-4
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST Murray NSL AGENCY Yavapai County Sheriff
DATE 2-4-08 TIME 9 39 13
INTOXILYZER SERIAL # 80-01734 LOCATION Seligman

1. Display Reads "PUSH BUTTON TO START"

DIAGNOSTIC TESTS

1. Clock time check.
 2. Date check.

OPERATIONAL TESTS

1. Alcohol-free subject test result 0. 000 AC.
 2. Error recognition logic system functioning.
Not a Successfully Completed Test Sequence printed
 3. Proper sample recognition system.
Not a Successfully Completed Test Sequence printed
Deficient sample printed.
 4. Standard Calibration Check standard 0. 100 AC. Result 0. 099 AC.

Instrument is operating properly and accurately. YES NO

COMMENTS 1st SOAP w/new tank # 2354016

SIGNATURE J. Murray

INTOXILYZER 8000

Location: YCSO SELIGMAN

Serial Number : 80-001734

02/04/2008

09:39:13

Standard Lot#: 735401G

Last Changed By: J. MURRAY

#N-56

QAS: J. MURRAY

#N-56

YAVAPAI CSO

Operator: J. MURRAY

#N-56

YAVAPAI CSO

Subject: SQAP,TEST

DOB: 11/20/1960

Sex: F

Weight: 115

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	09:40:41
Diagnostic Test	Pass	09:41:08
Air Blank	0.000	09:41:35
0.100 Cal Check	0.099	09:41:54
Air Blank	0.000	09:42:24
Subject Test	0.000	09:42:41
Air Blank	RFI*	09:42:57
Air Blank	IPS**	09:43:08

*RFI Detect

**Improper Sample

Not a Successfully Completed Test Sequence

INTOXILYZER 8000
Location: YCSO SELIGMAN
Serial Number : 80-001734
02/04/2008

09:43:55

Standard Lot#: 735401G
Last Changed By: J. MURRAY #N-56
QAS: J. MURRAY #N-56
YAVAPAI CSO

Operator: J. MURRAY #N-56
YAVAPAI CSO

Subject: SQAP,TEST
DOB: 10/20/1960
Sex: F Weight: 115

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	ABT*	09:44:43
Air Blank	0.000	09:45:11

*Sequence Aborted

Not a Successfully Completed Test Sequence

INTOXILYZER 8000
Location: YCSO SELIGMAN
Serial Number : 80-001734
02/04/2008

09:45:17

Standard Lot#: 735401G
Last Changed By: J. MURRAY #N-56

QAS: J. MURRAY #N-56
YAVAPAI CSO

Operator: J. MURRAY #N-56
YAVAPAI CSO

Subject: SQAP,TEST
DOB: 10/20/1960
Sex: F Weight: 115

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	09:46:10
Diagnostic Test	Pass	09:46:38
Air Blank	0.000	09:47:05
0.100 Cal Check	0.100	09:47:24
Air Blank	0.000	09:47:53
Subject Test	0.000*	09:51:02
Air Blank	0.000	09:51:35
Air Blank	0.000	09:52:02
Subject Test	XXX**	09:52:24
Air Blank	0.000	09:52:59

*Deficient Sample

**Invalid Sample

Begin new deprivation period

Not a Successfully Completed Test Sequence

EXHIBIT G-2
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST Murray NSB AGENCY Yavapai County Sheriff
DATE 2-4-08 TIME 9 54 22
INTOXILYZER SERIAL # 80-01734 LOCATION Seligman

- (X) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 100 AC.
OR
Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
- (X) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
- (X) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
- (X) 4. Air blank completed.
- (X) 5. Calibration check completed. Test results 0. 099 AC.
- (X) 6. Air blank completed.
- (X) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE J. Murray NSB

INTOXILYZER 8000

Location: YCSO SELIGMAN

Serial Number: 80-001734

02/04/2008

09:54:22


Standard Lot#: 735401G

Last Changed By: J. MURRAY #N-56

QAS: J. MURRAY #N-56

YAVAPAI CSO

Test	g/210L	Time
Air Blank	0.000	09:54:49
Cal Check	0.099	09:55:08
Air Blank	0.000	09:55:37



Operator's Signature

EXHIBIT G-2
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST Murray NSB AGENCY Yavapai County Sheriff
DATE 2-4-08 TIME 9:32:15
INTOXILYZER SERIAL # 80-01734 LOCATION Seligman

- (X) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 100 AC.
OR
Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
- (X) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
- (X) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
- (X) 4. Air blank completed.
- (X) 5. Calibration check completed. Test results 0. 099 AC.
- (X) 6. Air blank completed.
- (X) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE J. Murray NSB

INTOXILYZER 8000

Location: YCSO SELIGMAN

Serial Number: 80-001734

02/04/2008

09:32:15

Standard Lot#: 735401G

Last Changed By: J. MURRAY #N-56

QAS: J. MURRAY #N-56

YAVAPAI CSO

Test	g/210L	Time
Air Blank	0.000	09:32:42
Cal Check	0.099	09:33:01
Air Blank	0.000	09:33:31

J. Murray N56

Operator's Signature