

EXHIBIT G-2
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000
STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST T. LAWRENCE AGENCY Prescott Valley PD
DATE 6-7-15 TIME 1939
INTOXILYZER SERIAL # 80-000293 LOCATION PUPD/ Booking Room.

- (4) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 100 AC.
OR
Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
- (5) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
- (4) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
- (5) 4. Air blank completed.
- (4) 5. Calibration check completed. Test results 0. 099 AC.
- (4) 6. Air blank completed.
- (5) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE _____

DPS Form Exh G-2 (Rev 05-01)

* SEE NOTES.

INTOXILYZER 8000
Location: PRESCOTT VALLEY PD
Serial Number: 80-000293
Core Version: 8105.48
06/07/2015 19:35:12

Standard Lot#: 26614100A6
Last Changed By: A. LAWRENCE #61

QAS: A. LAWRENCE #61
PRESCOTT VALLEY PD

Operator: A. LAWRENCE #61
PRESCOTT VALLEY PD

Test	g/210L	Time
Air Blank	0.000	19:35:42
0.100 Cal Check	0.099	19:36:03
Air Blank	0.000	19:36:33

Preventative Maintenance NOT
Performed -- Timer NOT Reset

- 1st TEST AFTER INTOX 8000 STATED
CONTACT QAS / OUT OF TOLERANCE.
- INTOX SHOWED .099 CAL CHECK. w/
17 OF INTOX PERFECT.

INTOXILYZER 8000

Location: PRESCOTT VALLEY PD

Serial Number: 80-000293

Core Version: 8105.48

06/07/2015

19:39:45

Standard Lot#: 26614100A6

Last Changed By: A. LAWRENCE #61

QAS: A. LAWRENCE #61

PRESCOTT VALLEY PD

Operator: A. LAWRENCE #61

PRESCOTT VALLEY PD

Test	g/210L	Time
Air Blank	0.000	19:40:15
0.100 Cal Check	0.099	19:40:36
Air Blank	0.000	19:41:05

Preventative Maintenance
Performed -- Timer Reset

- 2ND TEST (SEE FIRST FOR DETAILS)

- AFTER 2ND TEST INTOX WAS
PUT BACK INTO SERVICE.

- NO ISSUES NOTED WITH EITHER TEST.