

EXHIBIT G-2
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST TOBIN #73 AGENCY PVPD
DATE 05-30-2008 TIME 12:53:57
INTOXILYZER SERIAL # 80-000293 LOCATION PVPD

- () 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 100 AC.
OR
Pour a standard alcohol concentration solution N/A AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
- () 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
- () 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
- () 4. Air blank completed.
- () 5. Calibration check completed. Test results 0. 099 AC.
- () 6. Air blank completed.
- () 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE [Signature] #73

INTOXILYZER 8000

Location: PRESCOTT VALLEY PD

Serial Number: 80-000293

05/30/2008

12:53:57

Standard Lot#: 706502I

Last Changed By: J. TOBIN #73

QAS: J. TOBIN #73

PRESCOTT VALLEY PD

Test	g/210L	Time
Air Blank	0.000	12:54:24
Cal Check	0.099	12:54:43
Air Blank	0.000	12:55:12

J. Tobin #73

Operator's Signature